

inputs: -----0-

A1 = 110001000
states: 100%

inputs: -----1-

A2,A3
A4
states: 17.1875%

A2
A4
states: 6.25%

A2
A3
states: 0.7812%

A3
A4
states: 17.1875%

A2 = 110001010
states: 50%

A4 = 110111110
states: 6.25%

A3 = 110101111
states: 2.3438%

